



# Axial-Bohr-und Fräskopf

Axial drilling and milling head

Tête de perçage et de fraisage axiale



Darstellung symbolisch  
symbolical drawing  
schéma symbolique



Befestigungsschrauben  
fastening screws  
vis de fixation

easy-quick HT4

bei externer Kühlmittelzufuhr Verschlusschraube durch Kühlrohr ersetzen  
using external coolant supply, please substitute locking screw by coolant tube  
pour arrosage externe, remplacez la vis par le tube fileté


Optionen :  
options :  
options :



Wechseleinsatz easy-quick  
insert easy-quick  
insert easy-quick




Bedienschlüssel  
wrench  
clé



» weitere Ausführungen auf Anfrage  
other models on request  
autres modèles sur demande

subject to technical changes



mit kombinierter Kühlmittelzufuhr  
with combined coolant supply  
arrosage combiné

p x n Diagramm D 00 002  
p x n diagram D 00 002  
p x n diagramme D 00 002

p max. [bar] = 25  
i = 1:1  
M<sub>2</sub> max. [Nm] = 16  
n<sub>2</sub> max. [min<sup>-1</sup>] = 8000

Bestell - Nr.  
ref.no. / No.de cde.

**8 010 46 277**

nous nous réservons toutes modifications techniques