


Axial-Bohr- und Fräskopf

Axial drilling and milling head


Tête de perçage et de fraisage axiale



Darstellung symbolisch
symbolical drawing
schéma symbolique




Gewindestift zum Abdrücken
thread screw to push away
vis pour écarter




easy-quick HT4

0
18
35
51



bei externer Kühlmittelzufuhr Verschlusschraube durch Kühlrohr ersetzen
using external coolant supply, please substitute locking screw by coolant tube
pour arrosage externe, remplacez la vis par le tube fileté



Optionen :
options :
options :



Wechseleinsatz easy-quick
insert easy-quick
insert easy-quick



Bedienchlüssel
wrench
clé

Technische Änderungen vorbehalten

» weitere Ausführungen auf Anfrage
other models on request
autres modèles sur demande

subject to technical changes

nous nous réservons toutes modifications techniques

Bestell - Nr.
ref.no. / No.de cde.

8 010 46 112

p max. = 25 bar
i = 1:1
M₂ max. = 50 Nm
n₂ max. = 6000 min⁻¹