


Axial-Bohr-und Fräskopf

Axial drilling and milling head


Tête de perçage et de fraisage axiale



Darstellung symbolisch
symbolical drawing
schéma symbolique



Optionen :
options :
options :





Wechseleinsatz easy-quick
insert easy-quick
insert easy-quick



Bedienschlüsselsatz
set of wrench
jeu de clés

bei externer Kühlmittelzufuhr Verschlusschraube durch Kühlrohr ersetzen
using external coolant supply, please substitute locking screw by coolant tube
pour arrosage externe, remplacez la vis par le tube fileté



$i \neq 1$

mit innerer Kühlmittelzufuhr für Hochdruck
internal coolant supply (for high pressure)
arrosage interne (pour haute pression)

mit kombinierter Kühlmittelzufuhr
with combined coolant supply
arrosage combiné

p x n Diagramm D 00 010
p x n diagram D 00 010
p x n diagramme D 00 010

$$n_2 = -\frac{1}{i} \times n_1$$

n_1

p max. [bar] = 140

i = 13

M₂ max. [Nm] = 16

n₂ max. [min⁻¹] = 15000

Bestell - Nr.
ref.no. / No.de cde.

8 019 46 224

» weitere Ausführungen auf Anfrage
other models on request
autres modèles sur demande

subject to technical changes

nous nous réservons toutes modifications techniques