



# Axial-Bohr-und Fräskopf

Axial drilling and milling head


Tête de perçage et de fraisage axiale



Darstellung symbolisch  
symbolical drawing  
schéma symbolique



bei externer Kühlmittelzufuhr Verschlusschraube durch Kühlrohr ersetzen  
using external coolant supply, please substitute locking screw by coolant tube  
pour arrosage externe, remplacez la vis par le tube fileté



$$n_2 = +n_1$$

Optionen :  
options :  
options :



Wechseleinsatz easy-quick  
insert easy-quick  
insert easy-quick



Bedienschlüssel  
wrench  
clé

» weitere Ausführungen auf Anfrage  
other models on request  
autres modèles sur demande

Technische Änderung vorbehalten

subject to technical changes

mit kombinierter Kühlmittelzufuhr  
with combined coolant supply  
arrosage combiné

p x n Diagramm D 00 003  
p x n diagram D 00 003  
p x n diagramme D 00 003

|                     |                      |   |      |
|---------------------|----------------------|---|------|
| p max.              | [bar]                | = | 25   |
| i                   |                      | = | 1:1  |
| M <sub>2</sub> max. | [Nm]                 | = | 50   |
| n <sub>2</sub> max. | [min <sup>-1</sup> ] | = | 6000 |

Bestell - Nr.  
ref.no. / No.de cde.

**8 010 47 103**

nous nous réservons toutes modifications techniques