



Winkel- Fräs- und Bohrkopf

Radial milling and drilling head

Tête de perçage et de fraisage radiale




Darstellung symbolisch
symbolical drawing
schéma symbolique




bei externer Kühlmittelzufuhr Schraube entfernen
for external coolant supply, take off screw
pour arrosage externe, enlevez la vis

easy-quick HT4



Befestigungsschrauben
fastening screws
vis de fixation



i = 1:1
M₂ max. [Nm] = 50
n₂ max. [min⁻¹] = 6000

Bestell - Nr.
ref.no. / No.de cde.

8 030 46 413

Optionen :
options :
options :



Wechseleinsatz easy-quick
insert easy-quick
insert easy-quick



Bedienschlüsselsatz
set of wrench
jeu de clés

» weitere Ausführungen auf Anfrage
other models on request
autres modèles sur demande

Technische Änderung vorbehalten

subject to technical changes

nous nous réservons toutes modifications techniques