



Axial-Bohr-und Fräskopf

Axial drilling and milling head

Tête de perçage et de fraisage axiale



Darstellung symbolisch
symbolical drawing
schéma symbolique



Optionen :
options :
options :



Dichtscheiben
sealings
joints



Spannzangen
collets
Les pinces




Bedienschlüsselsatz
set of wrench
jeu de clés




Wechseleinsatz u-tec
insert u-tec
insert u-tec

bei externer Kühlmittelzufuhr Schraube entfernen
for external coolant supply, take off screw
pour arrosage externe, enlevez la vis



ER 25 A UT (0,5 - 16,0)

n_2



$i \neq 1$

mit innerer Kühlmittelzufuhr für Hochdruck
internal coolant supply (for high pressure)
arrosage interne (pour haute pression)

mit kombinierter Kühlmittelzufuhr
with combined coolant supply
arrosage combiné

p x n Diagramm D 00 010
p x n diagram D 00 010
p x n diagramme D 00 010

Befestigungsschrauben
fastening screws
vis de fixation

$$n_2 = -\frac{1}{i} \times n_1$$

p max. [bar] = 140

i = 2:1

M₂ max. [Nm] = 50

n_2 max. [min⁻¹] = 3000

Bestell - Nr.
ref.no. / No.de cde.

8 019 55 029

» weitere Ausführungen auf Anfrage
other models on request
autres modèles sur demande

subject to technical changes

nous nous réservons toutes modifications techniques