



Axial-Bohr-und Fräskopf

Axial drilling and milling head

Tête de perçage et de fraisage axiale



Darstellung symbolisch
symbolical drawing
schéma symbolique




Optionen :
options :
options :



Wechseleinsatz easy-quick
insert easy-quick
insert easy-quick





Bedienschlüssel
wrench
clé



bei externer Kühlmittelzufuhr Verschlusschraube durch Kühlrohr ersetzen
using external coolant supply, please substitute locking screw by coolant tube
pour arrosage externe, remplacez la vis par le tube fileté

» weitere Ausführungen auf Anfrage
other models on request
autres modèles sur demande



mit innerer Kühlmittelzufuhr für Hochdruck
internal coolant supply (for high pressure)
arrosage interne (pour haute pression)

mit kombinierter Kühlmittelzufuhr
with combined coolant supply
arrosage combiné

p x n Diagramm D 00 010
p x n diagram D 00 010
p x n diagramme D 00 010

$$n_2 = -n_1$$



p max. [bar] = 140

i = 1:2

M₂ max. [Nm] = 50

n₂ max. [min⁻¹] = 8000

Bestell - Nr.
ref.no. / No.de cde.

8 019 59 000

nous nous réservons toutes modifications techniques

Technische Änderung vorbehalten

subject to technical changes