

Winkel- Bohr- und Fräskopf

Radial drilling and milling head



Tête de perçage et de fraiseage radiale



Darstellung symbolisch
symbolical drawing
schéma symbolique

bei externer Kühlmittelzufuhr Verschliessschraube durch Kühlrohr ersetzen
using external coolant supply, please substitute locking screw by coolant tube
pour arrosage externe, remplacez la vis par le tube fileté

easy-quick HT6



Optionen :
options :
options :



Wechseleinsatz easy-quick
insert easy-quick
insert easy-quick



Bedienchlüssel
wrench
clé

Technische Änderung vorbehalten

» weitere Ausführungen auf Anfrage
other models on request
autres modèles sur demande

subject to technical changes

p max. [bar] = 140
i = 1:1
M₂ max. [Nm] = 50
n₂ max. [min⁻¹] = 6000

Bestell - Nr.

ref.no. / No de cde.

8 033 48 004

nous nous réservons toutes modifications techniques