





Winkel- Bohr- und Fräskopf

Radial drilling and milling head

Tête de perçage et de fraisage radiale



Darstellung symbolisch
symbolical drawing
schéma symbolique



easy-quick HT6

Optionen :
options :
options :

bei externer Kühlmittelzufuhr Verschlusschraube durch Kühlrohr ersetzen
using external coolant supply, please substitute locking screw by coolant tube
pour arrosage externe, remplacez la vis par le tube fileté



Wechseleinsatz easy-quick
insert easy-quick
insert easy-quick





Bedienschlüssel
wrench
clé

» weitere Ausführungen auf Anfrage
other models on request
autres modèles sur demande

Technische Änderung vorbehalten


subject to technical changes



mit innerer Kühlmittelzufuhr für Hochdruck
internal coolant supply (for high pressure)
arrosage interne (pour haute pression)

mit kombinierter Kühlmittelzufuhr
with combined coolant supply
arrosage combiné

p x n Diagramm D 00 010
p x n diagram D 00 010
p x n diagramme D 00 010



$n_2 = +n_1$
 n_1

p max. [bar] = 140

i = 1:1

M₂ max. [Nm] = 50

n₂ max. [min⁻¹] = 4000

Bestell - Nr.
ref.no. / No.de cde.

8 033 58 014

nous nous réservons toutes modifications techniques